






Componenti quadro di campo 2 stringhe 1000V DC:

- 1 cassetta in poliestere IP65 7511023 (380x285x185 mm)
- 1 piastra di fondo in metallo 7432023
- 1 piastra di fondo isolante 7431023
- 4 portafusibili unipolari 2401038D 1000V DC
- 1 sezionatore DC-21B 3450160 1000V DC 30A max
- 1 manovra diretta 3591201
- 1 scaricatore di sovratensione 1000V DC classe II 2445208
- 2 barre parallelo 2306035/2
- 3 connettori MC4 maschio 1002700
- 3 connettori MC4 femmina 1002710
- 1 pressacavo M16 1002102 (per uscita cavo messa a terra)
- 1 ghiera M16 1002152
- Cavo solare FG21M21 6 mmq
- Quadro fornito cablato come da disegno (indicativo)

Components for string box for 2 strings 1000V DC:

- 1 polyester enclosure IP65 7511023 (380x285x185 mm)
- 1 metal mounting plate 7432023
- 1 insulating mounting plate 7431023
- 4 single pole fuseholders 2401038D 1000V DC
- 1 switch-disconnector DC-21B 3450160 1000V DC 30A
- 1 direct handle 3591201
- 1 surge arrester 1000V DC class II 2445208
- 2 parallel busbars 2306035/2
- 3 male connectors MC4 1002700
- 3 female connectors MC4 1002710
- 1 cable gland M16 1002102 (for earthing cable)
- 1 lock nut M16 1002152
- Solar cable FG21M21 6 mmq
- String box delivered with cabling as indicated in the drawing

I fusibili sono da acquistare a parte / Fuses must be purchased separately

ITALWEBER

Via E. Fermi, 40/42
I - 20090 Assago MI
Italia / Italy

Tel. ++39-02-93977.1
Fax ++39-02-93904564/5
e-mail: info@italweber.it

Codice: 7852088

Disegnato: _____

Approvato: _____

Data: 23/11/2009

Rev. 0

Pag. 1 di 1